


# A2.8 Surface Curvature Analysis

The Diagnostic Shading Curvature Evaluation tool is complex to use and interpret, and will give different results depending on the 'Type' setting that you choose:



In this tutorial, Barry explains which settings to use to analyse the quality of your surfaces.

## INDEX

Time	Topic	Menu/Palette	Tool	Options
0.15	Example geometry			
1.10	Gaussian Shader on the example geometry	Control Panel > Diagnostic Shade	<b>Curvature Evaluation</b>	Gaussian
1.38	Discussing the importance of the direction of evaluation			
2.55	Mean Shader on the example geometry	Control Panel > Diagnostic Shade	<b>Curvature Evaluation</b>	Mean
3.50	Principal Minimum Shader on the example geometry	Control Panel > Diagnostic Shade	<b>Curvature Evaluation</b>	Princ. Min.
4.57	Principal Maximum Shader on the example geometry	Control Panel > Diagnostic Shade	<b>Curvature Evaluation</b>	Princ. max
5.45	Discussing of how the direction of evaluation affects the results			
	Saddle Surface			
6.19	Mean shader on the saddle surface	Control Panel > Diagnostic Shade	<b>Curvature Evaluation</b>	Mean
7.45	Estimating the inflection point by eye, for comparison			
8.09	Gaussian shader on the saddle surface	Control Panel > Diagnostic Shade	<b>Curvature Evaluation</b>	Gaussian
	Truck Surfaces			
8.46	Using Curvature plots to analyse highlights?			
9.09	Using Curvature plots to diagnose transitions			
9.20	Gaussian shader on the truck surfaces	Control Panel > Diagnostic Shade	<b>Curvature Evaluation</b>	Gaussian
9.44	The problem with using Gaussian for analysing transitions			
11.04	Principal Minimum shader on the truck surfaces	Control Panel > Diagnostic Shade	<b>Curvature Evaluation</b>	Princ. Min.
11.37	Principal Maximum shader on the truck surfaces	Control Panel > Diagnostic Shade	<b>Curvature Evaluation</b>	Princ. max